



Display

Video Products Technical Bulletin 30-2003-006

DATE: **January 8, 2003**SUBJECT: **SOFTWARE UPGRADE—FROM VERSION 1.20 TO
VERSION 1.21 ONLY**

MODEL: ***BVM-D20F1A/1***
BVM-D20F1E/1
BVM-D20F1E/2
BVM-D20F1U/1
BVM-D24E1WA
BVM-D24E1WE
BVM-D24E1WU
BVM-D32E1WA
BVM-D32E1WE
BVM-D32E1WU

SERIAL NO:

BVM-D20F1A/1 2,010,119–2,010,147
BVM-D20F1E/1 2,010,022–2,010,052
BVM-D20F1E/2 2,010,053–2,010,064
 BVM-D20F1U/1 2,010,001–2,010,175
BVM-D24E1WA 2,000,066–2,000,093
BVM-D24E1WE 2,000,231–2,000,388
 BVM-D24E1WU 2,000,449–2,000,604
BVM-D32E1WA 2,000,002–2,000,003
BVM-D32E1WE 2,000,034–2,000,051
 BVM-D32E1WU 2,000,228–2,000,255

*Italicized information in green applies to
customers outside the United States.*

DESCRIPTION

Upgrade software from V1.20 to V1.21 to implement the following improvements.

- From stand-by mode, the monitor control unit power switch starts the unit up normally.
- When the BKM-21D is installed, all control items on the BKM-21D maintenance menu are active.

NOTE: These improvements are needed only on units with V1.20. Upgrade the version to V1.21 only.

PARTS REQUIRED

Part No.	Description	Qty.
MBVMD2/2	V1.20 to V1.21 Upgrade	1

ORDERING INFORMATION

To order upgrades, contact:

Sony **SOFTWAREPLUS**[®] Center

Fax: 816-880-6854

Call: 800-538-7550 → Option 5

Mail: Sony **SOFTWAREPLUS**[®] Center

8281 NW 107th Terrace

Kansas City, MO 64153

Customers outside the United States: Please order parts from your usual supplier.

MODIFICATION PROCEDURE AND CONFIRMATION

Refer to Technical Bulletin 30-1998-241R.

DPMO02-049