



Display

## Video Products Technical Bulletin 30-2002-051

DATE: **May 13, 2002**SUBJECT: **SAVE T602 FROM FORMER FE BOARD FOR  
MOUNTING ON NEW FE BOARD**MODEL: ***PVM-1440QM***  
***PVM-1442QM***  
***PVM-1444QM***SERIAL NO: **ALL**

*Italicized information in green applies to  
customers outside the United States.*

**DESCRIPTION**

T602 (horizontal drive transformer, 1-437-090-31) is no longer available as an individual component, and new FE boards (A-1245-456-C) no longer contain T602.

Therefore, when replacing the FE board, remove T602 from the former FE board and mount it on the new FE board.

DPM001-061