

BVM-D20F1 BVM-D24E1W BVM-D32E1W

Version 1.20 Software Upgrade

Sony Business Solutions & Systems Company (BSSC) is pleased to announce that the V1.20 software upgrade is available. In order to enjoy the benefits of software improvements, it is important to keep your software current.

New Features

HDW COLOR BAR Setting

A setting for HDW COLOR BAR is added to the Control Preset Adjustment menu for use with the quasi SMPTE color bar signal output from HDCU-900.

Precision Adjustments

Precision adjustments for contrast, brightness, color temperature, and other settings are now available.

Display of Color Temperature Data

When adjusting STD, COL1, COL2, AND CH SET color temperature data, the selected color temperature data is now displayed at the top of the picture to allow confirmation that the correct data is adjusted. When adjusting Control Preset data, PRESET or CH SET is displayed at the top of the picture for confirmation.

Version Release

| Model | Kit ID | Upgrade Kit Description |
|---------------------------------------|----------|--------------------------|
| BVM-D20F1 BVM-D24E1W BVM-D32E1W | MBVMD2/1 | SRAM Card Software V1.20 |

**Optional Support
Services**

For installation by Sony field service personnel, contact your Sony Regional Service Center to schedule installation after ordering/receiving your upgrades.

To Order Upgrades

Sony **SOFTWAREPLUS**[®] Center

Fax: 816-880-6854

Call: 800-538-7550 → Option 5

Mail: Sony **SOFTWAREPLUS[®] Center**

8281 NW 107th Terrace

Kansas City, MO 64153

Customers outside the United States: *Please order parts from your usual supplier.*